Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	4833	(plural\$4 three couple multiple array) near3 (load force pressure strain stress) near3 (cell gauge sens\$4 detect\$4 measur\$4 transducer).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 11:11
L2	1905	1 and (vertical\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 10:55
L3	99	2 and (pin).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 10:56
L4	36	2 and (load\$4 pressure force strain stress) near3 (pin).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 11:01
L5	2	"6532830"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 10:57
L6	9544	(load\$4 pressure force strain stress) near3 (pin).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 11:01
L7	2642	6 and (plate).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 11:02
L8	19	7 and (plural\$4 three couple multiple array four\$4) near3 (load force pressure strain stress) near3 (cell gauge sens\$4 detect\$4 measur\$4 transducer).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 11:02
L9	11	8 and (two plural\$4 top bottom inner outer) near3 (plate)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 11:02

L10	179	1 and (pin).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 11:13
L11	151	10 and (plate support\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 11:10
L12	162	"5315882" "5078016" "4623813" "4488441" "4094192" "3960456" "3956930" "3640130" "3618376"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 11:11
L13	81	12 and (plural\$4 three couple multiple array) near3 (load force pressure strain stress) near3 (cell gauge sens\$4 detect\$4 measur\$4 transducer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 11:12
L14	6	13 and (pin).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 11:13
L15	29	13 and (pin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/12/01 11:14